APPENDIX H

CONCRETE SITE ANALYSIS

PREPARED BY MILLER DUNWIDDIE ARCHITECTURE

2016

this page left blank intentionally

KEY

- (A) CRACK
- (B) SPALL
- (C) FAILED SEALANT JOINT
- (D) PATCH
- (E) UNMATCHING PATCH

A,C
B
B
A,C

A,C
A
A,C
B

B
B
B
B
B
B
A,C
A,C
A

B
B
C

C

A,C
A,C
B

B

C
B

B
A.C
A
C
B
C

A
A

A
E

A
A

A
A
A
A
A
B

A
A
A
B

C
A

B
B
B
A
C
A,B
A

A
A
A
A
A

DOUBLETREE
SUITES
A
B
B

B
B
A

A
A


A
E
A
A

3

C
C

B
B
B
B
B
C
E


B
C

F-1
A
B
A
B
A,B
E
E
E
E
E
E
A

KEEP OFF
AUTHORIZED
PERSONEL
ONLY
A
A
A
A
A
F-2

F-3
E
A
A
A

F-4

F-5

F-6

F-7

F-8

A
E

KEEP OUT
A
A
A
D
F-10

A

A
A
A

C
A
A

F-14

A
A
D
CAUTION
KEEP OUT

A
E
CAUTION
KEEP OUT

A
A
A
E
A
A
E